


Camshaft LH

Forge
2in Xtralife





Related Items

Automann #	Image	Product Name
123.282318.04	1.125" A = 2.250" -1.625" Dia. 1.500" A 1.500" A 2.500" B 2.500"	Camshaft RH
110.2010		Camshaft Repair Kit

© 2024 Automann USA, Inc. 1 of 3

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. When ordering, customers have the option to order using industry references, OEM references or Automann references.

Automann #	Image	Product Name
110.2303		Camshaft Repair Kit

Specifications

Attribute	Value
Applications	Dana/Spicer
Head Style	Head Style 6
Head Type	1.125" Extended Life, Hendrickson HXS
Length (L)	23.563"
Length (A)	2.250"
Splines	1.500"-28
Journal Dia. (A)	1.625"
Journal Dia. (B)	1.500"
Hardware Kit(s)	110.2303,110.2010 w/ Brackets

Where Used

This item is featured in the following schematics:

Name	Туре
Dana Spicer Trailer Axle 16-1/2" X 7" / FMSI 4707 ("XL II" Double Anchor Pin)	Brake

Series

There is no series data for this product.

Cross Reference

Name	Part Number	Notes
Euclid	E9735	Camshaft

© 2024 Automann USA, Inc. 2 of 3

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. When ordering, customers have the option to order using industry references, OEM references or Automann references.

Name	Part Number	Notes
Haldex	CS41420	Camshaft
Meritor	R607231	Camshaft
Spicer	17-929	Camshaft
Spicer	M16WKL25236	Camshaft
Spicer	M16WKL25-236	Camshaft

© 2024 Automann USA, Inc. 3 of 3