

Camshaft Repair Kit

A	440.0046	
Automann #	110.2216	
UPC Code	889626004568	
Categories	Air Brake & Wheel > Camshaft Repair Kits > Meritor Browse By Brand > Automann	
Brand	Automann	
Product Level	Fleet Standard	
Description	• TRAILER Meritor 16-1/2in P Type with 1-1/2in Camshaft	
Ref. #	E2088A, CQ67328	
Applications	Meritor	
Shipping	Parcel friendly	
Unit Size	1	
Weight	2.2 lbs	
Pkg. Dims (in) Pkg. Dims (in)	9.75 X 4.25 X 2.75	
Arrival Date	July 2005	



Related Items

Automann #	Image	Product Name
110.2008	0000	Camshaft Repair Kit
110.2009	0000	Camshaft Repair Kit

© 2024 Automann USA, Inc. 1 of 6

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. When ordering, customers have the option to order using industry references, OEM references or Automann references.

Automann #	lmage	Product Name
110.2302		Camshaft Repair Kit
120.102012.01	A = 1,625" 8 = 2,313" 20,376" 1,500"-10 FERNAL MARKANINA	Camshaft LH
120.102012.02	1.375* A = 1,425* B = 2.313* A = 1,500* 1.500*-10 **Ellis Management*	Camshaft RH
122.101724.01	A = 2.219" 17.750" 1.500" Dia. 1.500" Dia.	Camshaft LH
122.101724.02	1.375° A = 2.219° 17.750° 1.500° Dia. 1.500° Dia.	Camshaft RH
122.102212.01	1.375" A = 2.219" 22.375" 1.300 Fig. 5.3114 h Amazum. No.	Camshaft LH
122.102212.02	1.375" A = 2.219" 22.375" 1.300"-10 1.300"-10	Camshaft RH
122.102524.01	1.375° A = 2.219° 25.750° L1.500° Dia. 1.500°10	Camshaft LH
122.102524.02	1.375° A = 2.219° 25.750° 1.300° Dia. 1.300° Dia. 1.315°	Camshaft RH

© 2024 Automann USA, Inc. 2 of 6

Automann #	Image	Product Name
124.100713.01	1.375" A = 1.225" B = 2.219 A = 1.500" Dia. 1.500" Dia	Camshaft LH
124.100713.02	1.375° A = 1.225° B = 2.210	Camshaft RH
124.101610.01	×	Camshaft LH
124.101610.02	×	Camshaft RH
124.101616.01	1.375" A = 2.219" 1.500" bio. 1.500" bio. 2.500 bio.	Camshaft LH
124.101616.02	1.375° A = 2.217° 1.500° Dia. 1.500° Dia	Camshaft RH
124.101712.01	1.375° A = 2.219° A = 17.378′ L1.500° Dio. 1.500° Tio	Camshaft LH
124.101712.02	1.375" A = 2.219" 1.500" Dia. 1.500" Dia	Camshaft RH
124.101812.01	1.375° A = 2.219° 18.375° 1.500° Dio. 1.500° Di	Camshaft LH
124.101820.01	1.375° A = 2.219° 18.625° L1.500° Dia. 1500° Di	Camshaft LH
124.101820.02	1.375° A = 2.219° 18.625	Camshaft RH

© 2024 Automann USA, Inc. 3 of 6

Automann #	Image	Product Name
124.102014.01	1,375" A = 1,625" B = 2,189" 20,489" 1,360"-10 2071 th hamman.	Camshaft LH
124.102014.02	A = 1.625° B = 2.169°	Camshaft RH
124.102014.03	A = 1.425° B = 2.188° -1.500° Dig. 13.00°-10	Camshaft LH
124.102014.04	1.188" A = 1.625 B = 2.188" A - 1.500" Dio. 1.300"-10	Camshaft RH
124.102103.01	1.375° A = 2219° 21.078° 1.500° Dig. 1.500° Dig.	Camshaft LH
124.102103.02	1.375° A = 2.219° 21.094° 1.300° Dia. 1.300° Dia.	Camshaft RH
124.102202.01	×	Camshaft LH
124.102202.02	×	Camshaft RH
124.102228.01	1.375° A = 2.219° 22.878 1.300° Do. 1.300° Tol.	Camshaft LH
124.102228.02	1.375° A = 2.219° 2.875° 1.300° Dia. 1.500° Dia. 2.219 Managana	Camshaft RH
124.102314.01	A = 1,625° B = 2219° C = 23,438 Ada, 12,00° Día. 12,00° Día.	Camshaft LH

© 2024 Automann USA, Inc. 4 of 6

Specifications

Attribute	Value
Applications	Meritor

Kit Consists Of

Automann #	Image	Product Name	QTY
111.0001	2.500°	Camshaft Bracket HD Style	2
112.1169	LD: 1.500° OD: 1.750° Lengthy 1.180°	Camshaft Bushing	2
112.1241	LD: 1.790° O.D: 1.500° Length 1.312°	Camshaft Bushing	2
113.1242	IQ: 1.50° O.D: 1.750° Phickness 0.140° mr.	Camshaft Seal	2
113.1281	ID: 1.500° O.D. 1.875° Trickness to 180°	Camshaft Seal	2
114.1174	LD: 1.531* O.D: 2.250* Trickness: 0.063*	Washer	8
115.1121	ID. 1.385* Wicross D. 100*	Camshaft Lock HD Version Of 115.1161	2

© 2024 Automann USA, Inc. 5 of 6



Where Used

This item is featured in the following schematics:

Name	Туре
Meritor Drive Axle 16-1/2" x 7" FMSI 4515E ("P" Series Double Anchor Pin)	Brake
Meritor Trailer Axle 16-1/2" X 7" / FMSI 4515E ("P" Series Double Anchor Pin)	Brake

Series

There is no series data for this product.

Cross Reference

Name	Part Number	Notes
Euclid	E2088A	Camshaft Repair Kit
Euclid	E2088AHD	Camshaft Repair Kit
Haldex	CQ67328	Camshaft Repair Kit
Meritor	KIT8046	Camshaft Repair Kit
Spicer	437044	Camshaft Repair Kit

© 2024 Automann USA, Inc. 6 of 6