

Camshaft Repair Kit

Automann #	110.2206
UPC Code	889626004476
Categories	Air Brake & Wheel > Camshaft Repair Kits > Meritor Browse By Brand > Automann
Brand	Automann
Product Level	Fleet Standard
Description	 Late Model 4000-6000 Trailer Axles w/1-5/8" Dia. Camshafts Alternate Spider Bushing to Kit 110.2204
Ref. #	E3989AHD, KIT8048
Applications	Meritor
Shipping	Parcel friendly
Unit Size	1
Weight	2.1 lbs
Pkg. Dims (in) Pkg. Dims (in)	9.562 X 4.062 X 2.625
Arrival Date	July 2005





Related Items

Automann #	Image	Product Name
110.2204		Camshaft Repair Kit
110.2209		Camshaft Repair Kit

© 2024 Automann USA, Inc. 1 of 6

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. When ordering, customers have the option to order using industry references, OEM references or Automann references.

Automann #	Image	Product Name
110.2010		Camshaft Repair Kit
110.2214		Camshaft Repair Kit
122.101710.01	A = 1.704" 1.375" A = 1.704" 1.305" Dia. 1.500" Dia	Camshaft LH
122.101710.02	A = 1.704* A = 1.7315 A = 1.225* Dia. 1.500* 1.00* 1	Camshaft RH
122.101710.03	A = 1.704" 17.313	Camshaft LH
122.101710.04	A = 1.704" A = 1.704" 17.313	Camshaft RH
122.102012.01	×	Camshaft LH
122.102012.02	×	Camshaft RH
122.102013.03	A = 1.704" A = 1.704" 1.188" 1.180" 1.500"	Camshaft LH
122.102013.04	1.188° A = 1.704° \[\frac{\Delta_1}{\Delta_1} \] \[\frac{\Delta_2}{\Delta_1} \] \[\frac{\Delta_2}{\Delta_2} \] \[\Del	Camshaft RH
122.102402.01	A = 1.704" A = 1.704" 1.500" 1.500" 2.718 t Marketonico.	Camshaft LH

© 2024 Automann USA, Inc. 2 of 6

Automann #	Image	Product Name
122.102402.02	A=1,704" 24,005 4-1,425" Dia. 1,500"	Camshaft RH
122.102402.03	A=1,704" A=1,704" 1,188" 1,185" Dia. 1,500"-10 1,500"-10 1,500"-10	Camshaft LH
122.102402.04	A=1,704*** 24,005*** 1,500**-1,250*-10 ESTIMATE ALLERS TO BE ALLERS TO	Camshaft RH
122.281710.01	A = 1,703" 8 = 1,969" 17,313" 1,625" Dia. 1,500" A 1,500" A 1,500" A	Camshaft LH
122.281710.02	A = 1,703 B = 1,969" 17,313 1,500 1,500 1,500 2,500 1,	Camshaft RH
122.281710.03	A=1703' B=1799' 17.513 1.500 1.500 1.500 2.8	Camshaft LH
122.281710.04	1.188° A = 1,703° B = 1,990° 17,313° 1,525° Dia. 1,500° Å 1,500° A	Camshaft RH
122.282012.02	0.488° A = 1.719°	Camshaft RH
122.282013.01	1.278" A = 1.700" B = 1.700" 20.407 1.500" 1	Camshaft LH

© 2024 Automann USA, Inc. 3 of 6

Automann #	Image	Product Name
122.282013.02	1.375° A = 1.700° B = 1.949° 1.425° Dia, 1.500° 28 62314 Marson, Inc.	Camshaft RH
122.282013.03	1.188" A = 1.700" B = 1.959" A = 1.200" A =	Camshaft LH
122.282013.04	A = 1,700° B = 1,949° 20,407° A = 1,700° A = 1,700° 20,407° A = 1,200° 20,400° A = 1,200° 20,400° A = 1,200° A = 1,200°	Camshaft RH
122.282302.01	×	Camshaft LH
122.282302.02	×	Camshaft RH
122.282307.01	A = 1.719" A = 1.719" A = 1.500" 1.500" 1.500" (-1.625" Dia. 1.500"	Camshaft LH
122.282307.02	0.688* A = 1.719* 23.219 1-1.625* Dia. 1.500*2	Camshaft RH
122.282402.01	A = 1,703° B = 1,939° 2 1,625° Dio. 1,500° 28 1,500° 28 6231 (ABRAIL) 1,500° 28 6231 (ABRAIL) 1,500° 28 6231 (ABRAIL) 1,500° 28	Camshaft LH
122.282402.02	1.275" A = 1,700" B = 1,959" 24,068 1.500" 1.500" 1.500" 2.500"	Camshaft RH
122.282402.03	1.188° A = 1.703° B = 1.969° -24.068° -1.625° Dio. 1.500°-28° -1.5	Camshaft LH
122.282402.04	1.188* A = 1.703* B = 1.939* 24.065* 1.500*23 1.500*23 1.500*23	Camshaft RH

© 2024 Automann USA, Inc. 4 of 6

Specifications

Attribute	Value
Applications	Meritor

Kit Consists Of

Automann #	Image	Product Name	QTY
107.1091	LD: 1300° O.D. 1,875° Thickness (D00° _{mitty Annual})	Washer	2
108.1041	LD: 1.160* Trickness 0.046*	Lock Ring	2
111.0001	2.500°	Camshaft Bracket HD Style	2
112.1203	ID.11425* OD.2200* Length: 1.188*	Camshaft Bushing	2
113.2002	ID: 1593* O.D. 2.000* Thickness 0.187*	Camshaft Seal	4
114.1174	LD: 1.531* O.D: 2.250* Trickness 0.062*	Washer	2
114.1201	I.D.: 1427* O.D.: 2250* Thickness Oddo*	Washer	4

© 2024 Automann USA, Inc. 5 of 6



Where Used

This item is featured in the following schematics:

Name	Туре
Meritor Trailer Axle 16-1/2" X 7" / FMSI 4515E ("Q" Series Double Anchor Pin)	Brake

Series

There is no series data for this product.

Cross Reference

Name	Part Number	Notes
Euclid	E3989AHD	Camshaft Repair Kit
Meritor	KIT8048	Camshaft Repair Kit

© 2024 Automann USA, Inc. 6 of 6