



Camshaft Repair Kit

Automann #	110.2210
UPC Code	889626004513
Categories	Air Brake & Wheel > Camshaft Repair Kits > Meritor Browse By Brand > Automann
Brand	Automann
Product Level	Fleet Standard
Description	<ul style="list-style-type: none"> • TRAILER Meritor 16-1/2in Q and Q-Plus Type, with 3/8in-16 x 1.83in Self Tapping Bolt on Bushings • TN, TP, TQ, and TR Trailer Axles • Fabricated Spiders w/Metal Press-In Bushings
Ref. #	E9079HD, KIT8078A
Applications	Meritor
Shipping	Parcel friendly
Unit Size	1
Weight	5.4 lbs
Pkg. Dims (in) Pkg. Dims (in)	6.875 X 4.687 X 4
Arrival Date	July 2005



Related Items

Automann #	Image	Product Name
110.2206		Camshaft Repair Kit
110.2209		Camshaft Repair Kit

Automann #	Image	Product Name
122.281710.01		Camshaft LH
122.281710.02		Camshaft RH
122.281710.03		Camshaft LH
122.281710.04		Camshaft RH
122.282013.01		Camshaft LH
122.282013.02		Camshaft RH
122.282013.03		Camshaft LH
122.282013.04		Camshaft RH
122.282302.01		Camshaft LH
122.282302.02		Camshaft RH
122.282402.01		Camshaft LH

Automann #	Image	Product Name
122.282402.02		Camshaft RH
122.282402.03		Camshaft LH
122.282402.04		Camshaft RH

Specifications

Attribute	Value
Applications	Meritor

Kit Consists Of

Automann #	Image	Product Name	QTY
107.1091		Washer	2
108.1041		Lock Ring	2
109.6019		Self Tapping Bolt	8
111.0001		Camshaft Bracket HD Style	2

Automann #	Image	Product Name	QTY
112.1205		Camshaft Bushing	2
114.1174		Washer	2
114.1203		Washer	2
114.1205		Washer	2
115.1051		Camshaft Lock HD Version Of 115.1101	2
115.1201		Camshaft Lock	2

Where Used

This item is featured in the following schematics:

Name	Type
Meritor Trailer Axle 16-1/2" X 7" / FMSI 4707 ("Q Plus" Series Double Anchor Pin)	Brake

Series

There is no series data for this product.

Cross Reference

Name	Part Number	Notes
Euclid	E9079	Camshaft Repair Kit
Euclid	E9079HD	Camshaft Repair Kit
Meritor	KIT8078A	Camshaft Repair Kit